

place.

In order to provide enough support for the mast, a 14 foot hole was dug for the mast to slide into.

Nowadays, a lot of the original transmitting equipment has been dismantled and the only sign of the huge antenna are the concrete support slabs that are embedded into the ground. The ground is significant in itself that underneath the dirt is copper sheeting that surrounds the property so that the antenna could have a ground plane.